

Recommendation on storage and handling of labels

To ensure proper handling of the labels, we recommend to store them as follows:




Storage

- Label rolls should be stored flat one upon the other.
- Do not expose the label rolls to direct sun light and heat radiation
- Storage should be at a temperature of max. 20° Celsius and a relative humidity of about 50 % to avoid adhesive bleed.
- Plastic labels with particularly easy-flowing adhesives should be stored in a cool environment at a temperature of about 10° to max. 18° Celsius, not condensing and packed in plastic bags.
- Leave shrink-wrapped label rolls packed in films until use. Repack partly used rolls in plastic bags to avoid absorption of humidity.

Handling

- Make sure to evenly lift the material when taking it out of the transport packaging to avoid telescoping.
- Avoid additional „tensioning“ of the rolls to keep the tensile preloading.
- Make sure you have a clean, grease- and oilfree adhesion surface.

For further information please contact our technical advisers and department for labels and ribbons. Or visit us on our website at www.cab.de.



All specifications about delivery, design and technical data are given to the best of our current knowledge and are subject to change without prior notice. **For more information go to www.cab.de**